


How to take CMOS battery discharge

1 , Remove the MINI PC and find the battery on the motherboard, as shown below



2 , At the Interface, slowly pull out, as shown below, wait for more than 1 minute of discharge

